





- 1. Single Survey
- 2. Energy Report
- 3. Property Questionnaire



### survey report on:

Property address	17 Welbeck Street, Kilmarnock, KA1 3JN
------------------	--

Customer	Ms L Craig

	17 Welbeck Street, Kilmarnock, KA1 3JN
--	--

Prepared by	Harvey Donaldson and Gibson
-------------	-----------------------------



HARVEY DONALDSON & GIBSON CHARTERED SURVEYORS

17 Welbeck Street, Kilmarnock, KA1 3JN 20th November 2023 QV287882

### PART 1 - GENERAL

#### 1.1 THE SURVEYORS

The Seller has engaged the Surveyors to provide the Single Survey Report and a generic Mortgage Valuation Report for Lending Purposes. The Seller has also engaged the Surveyors to provide an Energy Report in the format prescribed by the accredited Energy Company.

The Surveyors are authorised to provide a transcript or retype of the generic Mortgage Valuation Report on to Lender specific pro-forma. Transcript reports are commonly requested by Brokers and Lenders. The transcript report will be in the format required by the Lender but will contain the same information, inspection date and valuation figure as the generic Mortgage Valuation Report and the Single Survey. The Surveyors will decline any transcript request which requires the provision of information additional to the information in the Report and the generic Mortgage Valuation Report until the Seller has conditionally accepted an offer to purchase made in writing.

Once the Seller has conditionally accepted an offer to purchase made in writing, the Purchaser's lender or conveyancer may request that the Surveyors provide general comment on standard appropriate supplementary documentation. In the event of a significant amount of documentation being provided to the Surveyors, an additional fee may be incurred by the Purchaser. Any additional fee will be agreed in writing.

If information is provided to the Surveyors during the conveyancing process which materially affects the valuation stated in the Report and generic Mortgage Valuation Report, the Surveyors reserve the right to reconsider the valuation. Where the Surveyors require to amend the valuation in consequence of such information, they will issue an amended Report and generic Mortgage Valuation Report to the Seller. It is the responsibility of the Seller to ensure that the amended Report and generic Mortgage Valuation Report are transmitted to every prospective Purchaser.

The individual Surveyor will be a member of the Royal Institution of Chartered Surveyors who is competent to survey, value and report upon Residential Property<sup>1</sup>.

If the Surveyors have had a previous business relationship within the past two years with the Seller or Seller's Agent or relative to the property, they will be obliged to indicate this by ticking the adjacent box.

The ultimate holding company of Harvey Donaldson & Gibson is Countrywide plc. In Scotland, Countrywide plc also own Slater Hogg & Howison and Countrywide North. A full list of estate agents owned or under franchise to Countrywide plc is available on request. Harvey Donaldson & Gibson trades as an entirely separate company and has no financial interest whatsoever in the disposal of the property being inspected.

The Surveyors have a written complaints handling procedure. This is available from the offices of the Surveyors at the address stated.

#### 1.2 THE REPORT

The Surveyors will not provide an amended Report on the Property, except to correct factual inaccuracies.

The Report will identify the nature and source of information relied upon in its preparation.

The Surveyor shall provide a Market Value of the Property, unless the condition of the Property is such that it would be inappropriate to do so. A final decision on whether a loan will be granted rests with the Lender who may impose retentions in line with their lending criteria. The date of condition and value of the property will be the date of inspection.

Prior to 1 December 2008, Purchasers have normally obtained their own report from their chosen Surveyor. By contrast, a Single Survey is instructed by the Seller and made available to all potential Purchasers in expectation that the successful Purchaser will have relied upon it. The Royal Institution of

<sup>1</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Codes of Conduct.

Х

Chartered Surveyors rules require disclosure of any potential conflict of interest when acting for the Seller and the Purchaser in the same transaction. The Single Survey may give rise to a conflict of interest and if this is of concern to any party they are advised to seek their own independent advice.

The Report and any expressions or assessments in it are not intended as advice to the Seller or Purchaser or any other person in relation to an asking price or any other sales or marketing decisions. The Report is based solely on the Property and is not to be relied upon in any manner whatsoever when considering the valuation or condition of any other property.

If certain minor matters are mentioned in the Report it should not be assumed that the Property is free of other minor defects.

Neither the whole nor any part of the Report may be published in any way, reproduced or distributed by any party other than the Seller, prospective purchasers and the Purchaser and their respective professional advisers without the prior written consent of the Surveyors.

#### 1.3 LIABILITY

The Report is prepared with the skill and care reasonably to be expected of a competent residential surveyor who is a member of the Royal Institution of Chartered Surveyors.

The Report is addressed to the Seller and was prepared in the expectation that it (or a complete copy) along with these Terms and Conditions (or a complete copy) would (or, as the case might be, would have been) be disclosed and delivered to:

- the Seller;
- any person(s) noting an interest in purchasing the Property from the Seller;
- any person(s) who make(s) (or on whose behalf is made) an offer to purchase the Property, whether or not that offer is accepted by the Seller;
- the Purchaser; and
- the professional advisers of any of these.

The Surveyors acknowledge that their duty of skill and care in relation to the Report is owed to the Seller and to the Purchaser. The Surveyors accept no responsibility or liability whatsoever in relation to the Report to persons other than the Seller and the Purchaser. The Seller and Purchaser should be aware that if a Lender seeks to rely on this Report they do so at their own risk. In particular, the Surveyors accept no responsibility or liability whatsoever to any Lender in relation to the Report. Any such Lender relies upon the Report entirely at their own risk.

#### 1.4 GENERIC MORTGAGE VALUATION REPORT

The Surveyors undertake to the Seller that they will prepare a generic Mortgage Valuation Report, which will be issued along with the Single Survey. It is the responsibility of the Seller to ensure that the generic Mortgage Valuation Report is provided to every potential Purchaser.

#### 1.5 TRANSCRIPT MORTGAGE VALUATION FOR LENDING PURPOSES

The Surveyors undertake that on being asked to do so by a prospective purchaser, or his/her professional advisor or Lender, they will prepare a Transcript Mortgage Valuation Report for Lending Purposes on terms and conditions to be agreed between the Surveyors and Lender and solely for the use of the Lender and upon which the Lender may rely. The decision as to whether finance will be provided is entirely a matter for the Lender. The Transcript Mortgage Valuation Report will be prepared from information

contained in the Report and the generic Mortgage Valuation Report.<sup>2</sup>

#### 1.6 INTELLECTUAL PROPERTY

All intellectual property rights whatsoever (including copyright) in and to the Report, excluding the headings and rubrics, are the exclusive property of the Surveyors and shall remain their exclusive property unless they assign the same to any other party in writing.

#### 1.7 PAYMENT

The Surveyors are entitled to refrain from delivering the Report to anyone until the fee and other charges for it notified to the Seller have been paid. Additional fees will be charged for subsequent inspections and Reports.

#### **1.8 CANCELLATION**

The Seller will be entitled to cancel the inspection by notifying the Surveyor's office at any time before the day of the inspection.

The Surveyor will be entitled not to proceed with the inspection (and will so report promptly to the Seller) if after arriving at the property, the Surveyor concludes that it is of a type of construction of which the Surveyor has insufficient specialist knowledge to be able to provide the inspection satisfactorily. The Surveyor will also be entitled not to proceed if after arriving at the property, the surveyor concludes that the property is exempt under Part 3 of The Housing (Scotland) Act 2006 as detailed in the (Prescribed Documents) Regulations 2008. If there is a potential threat to their health or personal safety, the inspection may be postponed or cancelled, at the Surveyor's discretion.

In the case of cancellation or the inspection not proceeding, the Surveyor will refund any fees paid by the Seller for the inspection and Report, except for expenses reasonably incurred and any fee due in light of the final paragraph of this section.

In the case of cancellation by the Seller, for whatever reason, after the inspection has taken place but before a written report is issued, the Surveyor will be entitled to raise an invoice equivalent to 80% of the agreed fee.

#### 1.9 PRECEDENCE

If there is any incompatibility between these Terms and Conditions and the Report, these Terms and Conditions take precedence.

#### 1.1 DEFINITIONS

- the "Lender" is the party who has provided or intends or proposes to provide financial assistance to the Purchaser towards the purchase of the Property and in whose favour a standard security will be granted over the Property;
- the "Transcript Mortgage Valuation Report for Lending Purposes" means a separate report, prepared by the Surveyor, prepared from information in the Report and the generic Mortgage Valuation Report, but in a style and format required by the Lender. The Transcript Mortgage Valuation Report for Lending Purposes will be prepared with the skill and care reasonably to be expected from a surveyor who is a member of the Royal Institution of Chartered Surveyors and who is competent to survey, value and report on the Property;
- the "Generic Mortgage Valuation Report" means a separate report, prepared by the Surveyor from information in the Report but in the Surveyor's own format;

<sup>&</sup>lt;sup>2</sup> Which shall be in accordance with the current RICS Valuation Standards (The Red Book) and RICS Rules of Conduct

### Terms and Conditions

- the "Market Value" is the estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion;
- the "Property" is the property which forms the subject of the Report;
- the "Purchaser" is the person (or persons) who enters into a contract to buy the Property from the Seller;
- a "prospective Purchaser" is anyone considering buying the Property;
- the "Report" is the report, of the kind described in Part 2 of these Terms and Conditions and in the form set out in part 1 of Schedule 1 of the Housing (Scotland) Act 2006 (Prescribed Documents) Regulations 2008;
- the "Seller" is/are the proprietor(s) of the Property;
- the "Surveyor" is the author of the Report on the Property; and
- the "Surveyors" are the firm or company of which the Surveyor is an employee, director, member or partner (unless the Surveyor is not an employee, director, member or partner, when the "Surveyors" means the Surveyor) whose details are set out at the head of the Report.
- the "Energy Report" is the advice given by the accredited Energy Company, based on information collected by the Surveyor during the Inspection, and also includes an Energy Performance Certificate, in a Government approved format.

### **PART 2 - DESCRIPTION OF THE REPORT**

#### 2.1 THE SERVICE

The Single Survey is a Report by an independent Surveyor, prepared in an objective way regarding the condition and value of the Property on the day of the inspection, and who is a member of the Royal Institution of Chartered Surveyors. It includes an Energy Report as required by Statute and this is in the format of the accredited Energy Company. In addition, the Surveyor has agreed to supply a generic Mortgage Valuation Report.

#### 2.2 THE INSPECTION

The Inspection is a general surface examination of those parts of the Property which are accessible: in other words, visible and readily available for examination from ground and floor levels, without risk of causing damage to the Property or injury to the Surveyor.

All references to visual inspection refer to an inspection from within the property at floor level and from ground level within the site and adjoining public areas, without the need to move any obstructions. Any references to left or right are taken facing the front of the property.

The Inspection is carried out with the Seller's permission, without causing damage to the building or contents. Furniture, stored items and insulation are not moved.

Unless identified in the report the Surveyor will assume that no harmful or hazardous materials have been used in the construction. The presence or possible consequences of any site contamination will not be

researched.

The Surveyor will not carry out an asbestos inspection, and will not be acting as an asbestos inspector in completing a Single Survey of properties that may fall within the Control of Asbestos in the Workplace Regulations. In the case of flats it will be assumed that there is a duty holder, as defined in the Regulations and that a Register of Asbestos and effective Management Plan is in place, which does not require any expenditure, or pose a significant risk to health. No enquiry of the duty holder will be made.

#### 2.3 THE REPORT

The Report will be prepared by the Surveyor who carried out the property inspection and will describe various aspects of the property as defined by the headings of the Single Survey report with the comments being general and unbiased. The report on the location, style and condition of the property, will be concise and will be restricted to matters that could have a material effect upon value and will omit items that, in the Surveyor's opinion, are not significant. If certain minor matters are mentioned, it should not be interpreted that the property is free of any other minor defects.

Throughout the Report, the following repair categories will be used to give an overall opinion of the state of repair and condition of the property.

- 1 <u>Category 3:</u> Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.
- 2 Category 2: Repairs or replacement requiring future attention, but estimates are still advised.
- 3 Category 1: No immediate action or repair is needed.

**WARNING:** If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions when the effect can be considerable.

Parts of the property, which cannot be seen or accessed, will not be reported upon and this will be stated. If the Surveyor suspects that a defect may exist within an unexposed area and which could have a material effect upon the value, he may recommend further investigation by specialist contractors.

#### 2.4 SERVICES

Surveyors are not equipped or qualified to test the services and therefore no comment can be interpreted as implying that the design, installation and function of the services are in accordance/compliance with regulations, safety and efficiency expectations. However, comment is made where there is cause to suspect significant defects or shortcomings with the installations. No tests are made of any services or appliances.

#### 2.5 ACCESSIBILITY

A section is included to help identify the basic information interested parties need to know to decide whether to view a property.

#### 2.6 ENERGY REPORT

A section is included that makes provision for an Energy Report, relative to the property. The Surveyor will collect physical data from the property and provide such data in a format required by an accredited Energy Company. The Surveyor cannot of course accept liability for any advice given by the Energy Company.

#### 2.7 VALUATION AND CONVEYANCER ISSUES

The last section of the Report contains matters considered relevant to the Conveyancer (Solicitor). It also contains the Surveyor's opinion both of the market value of the property and of the re-instatement cost, as defined below.

"Market Value" The estimated amount for which a property should exchange on the date of valuation between a willing buyer and a willing seller in an arm's-length transaction after proper marketing wherein the parties had each acted knowledgeably, prudently and without compulsion. In arriving at the opinion of the Market Value the Surveyor also makes various standard assumptions covering, for example, vacant possession; tenure and other legal considerations; contamination and hazardous materials; the condition of un-inspected parts; the right to use mains services; and the exclusion of curtains, carpets etc. from the valuation. In the case of flats, the following further assumptions are made that:

- There are rights of access and exit over all communal roadways, corridors, stairways etc. and to use communal grounds, parking areas, and other facilities;
- There are no particularly troublesome or unusual legal restrictions;
- There is no current dispute between the occupiers of the flats or any outstanding claims or losses; and the costs of repairs to the building are shared among the co-proprietors on an equitable basis.

Any additional assumption, or any found not to apply, is reported.

"Re-instatement cost" *is an estimate for insurance purposes of the current cost of rebuilding the Property in its present form* unless otherwise stated. This includes the cost of rebuilding the garage and permanent outbuildings, site clearance and professional fees, but excludes VAT (except on the fees).

Sellers or prospective Purchasers may consider it prudent to instruct a reinspection and revaluation after a period of 12 weeks (or sooner if appropriate) to reflect changing circumstances in the market and/or in the physical condition of the Property.

#### 1. Information and scope of inspection

This section tells you about the type, accommodation, neighbourhood, age and construction of the property. It also tells you about the extent of the inspection and highlights anything that the surveyor could not inspect.

All references to visual inspection refer to an inspection from within the property without moving any obstructions and externally from ground level within the site and adjoining public areas. Any references to left or right in a description of the exterior of the property refer to the view of someone standing facing that part of the property from the outside.

The inspection is carried out without causing damage to the building or its contents and without endangering the occupiers or the surveyor. Heavy furniture, stored items and insulation are not moved. Unless identified in the report the surveyor will assume that no harmful or hazardous materials or techniques have been used in the construction. The presence or possible consequences of any site contamination will not be researched.

Services such as TV/cable connection, internet connection, swimming pools and other leisure facilities etc. will not be inspected or reported on.

Description	The subjects comprise a purpose built upper floor flat, within a two storey detached building containing six flats in total.
Accommodation	Ground Floor: Entrance with staircase to first floor. First Floor: Hallway, living room, two bedrooms, kitchen and shower room.

	Gross internal floor area (m²)	54 approx.
--	--------------------------------	------------

Neighbourhood and location	The property is situated in a mixed residential/commercial location within the town of Kilmarnock. Local amenities are available within a reasonable distance.
	The property is located close to a water course (River Irvine).

Age	33 years approx.

Dry and bright.

Chimney stacks	None.
Roofing including roof space	The roof structure is pitched, timber supported and covered with concrete tiles incorporating lead-lined valley gutters.
	The roof space above the subject flat is insulated at ceiling joist level.
Rainwater fittings	Visually inspected with the aid of binoculars where

Rainwater fittings	Visually inspected with the aid of binoculars where appropriate.
	The rainwater fittings are plastic components.

Weather

Main walls	Visually inspected with the aid of binoculars where appropriate.
	Foundations and concealed parts were not exposed or inspected.
	The main walls are of traditional cavity brick/block construction.

Windows, external doors and joinery	Internal and external doors were opened and closed where keys were available.
	Random windows were opened and closed where possible.
	Doors and windows were not forced open.
	The windows and door are modern replacement uPVC framed double glazed units. The soffit and fascia boards are timber.

External decorations	Visually inspected.
	The external timbers have painted finishes.

Conservatories / porches	None.
Communal areas	None.

Garages and permanent outbuildings	None.

Outside areas and boundaries	Visually inspected.
	There are communal garden grounds bounded by timber fences. There is residents unallocated parking.

Ceilings	Visually inspected from floor level.
	The ceilings are of plasterboard construction.

Internal walls	Visually inspected from floor level.
	Using a moisture meter, walls were randomly tested for dampness where considered appropriate.
	The internal walls are of timber framed construction lined with plasterboard.

Floors including sub floors	The floors are of suspended timber construction. All floors were covered with fixed coverings.
	C C

Internal joinery and kitchen fittings	Built-in cupboards were looked into but no stored items were moved.
	Kitchen units were visually inspected excluding appliances.
	The internal doors are moulded units. The skirtings and door surrounds are moulded. The kitchen is fitted with a range of contemporary wall and base units.

Chimney breasts and fireplaces	None.
--------------------------------	-------

Internal decorations	Visually inspected.
	Painted and Artex finishes have been applied.

Cellars	None.

Electricity	Accessible parts of the wiring were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	A main supply is connected. The meter and consumer unit are located within a cupboard at the entrance of the property.


Gas	Accessible parts of the system were visually inspected without removing fittings. No tests whatsoever were carried out to the system or appliances. Visual inspection does not assess any services to make sure they work properly and efficiently and meet modern standards. If any services are turned off, the surveyor will state that in the report and will not turn them on.
	A main supply is connected. The meter is located in an external meter box.

Water, plumbing, bathroom fittings	Visual inspection of the accessible pipework, water tanks, cylinders and fittings without removing any insulation. No tests whatsoever were carried out to the system or appliances.
	The pipes are of copper and plastic materials.
	The shower room contains a three piece suite.

Heating and hot water	Accessible parts of the system were visually inspected apart from communal systems, which were not inspected.
	No tests whatsoever were carried out to the system or appliances.
	Central heating is by way of a wall mounted gas fired combination boiler located in the kitchen. This supplies a system of hot water radiators and also provides domestic hot water.

Drainage	Drainage covers etc were not lifted.
	Neither drains nor drainage systems were tested.
	The property is believed to be connected to mains drainage.
Fire, smoke and burglar alarms	Visually inspected.
	No tests whatsoever were carried out to the system or appliances.
	The property has smoke and heat detectors.
	Scottish government regulations came into effect on 1st February 2022, which requires each property to have linked smoke and heat detectors and if gas/carbon burning appliances are present then a carbon monoxide alarm fitted. Purchasers should satisfy themselves with regards to compliance.
	There is an old alarm system, which we understand is not in use.

Any additional limits to inspection	For flats / maisonettes
	Only the subject flat and internal communal areas giving access to the flat were inspected.
	If the roof space or under-building / basement is communal, reasonable and safe access is not always possible. If no inspection was possible, this will be stated. If no inspection was possible, the surveyor will assume that there are no defects that will have a material effect on the valuation.
	The building containing the flat, including any external communal areas, was visually inspected only to the extent that the surveyor is able to give an opinion on the general condition and standard of maintenance.
	The property was occupied, furnished with fitted floor coverings in all rooms. Cupboards were used for storage purposes.
	Our inspection of the roof space has been carried out from the access hatch position only on health and safety grounds. The inspection of this area was restricted by insulation materials.
	This report does not constitute a full and detailed description of the property and a structural investigation was not carried out. No inspection was undertaken of woodwork or other parts of the structure which are covered, unexposed or otherwise inaccessible and as a result no guarantee can be given that such parts of the structure are free from rot, beetle or other defects.
	It was dry on the date of inspection. Leakage and water penetration within roof spaces, around chimney breasts, window openings, etc are sometimes only visible during or immediately after, adverse weather conditions.
	The report does not include an asbestos inspection. However, asbestos was widely used in the building industry until around 2000, when it became a banned substance. If the possibility of asbestos based products has been reported within the limitations of the inspection and you have concerns you should engage a qualified asbestos surveyor.



#### 2. Condition

This section identifies problems and tells you about the urgency of any repairs by using one of the following three categories:

Category 3	Category 2	Category 1
Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.	Repairs or replacement requiring future attention, but estimates are still advised.	No immediate action or repair is needed.

Structural movement	
Repair category	1
Notes	No visible evidence of significant structural movement was noted within the limitations of the inspection.
	All buildings move seasonally as a result of external factors such as gravity, temperature, moisture content and vibrations. Consequently most buildings will have some minor cracks related to these factors. Minor cracks can be filled but often recur seasonally due to normal movement in a building.

Dampness, rot and infestation	
Repair category	1
Notes	None noted within the limitations of the inspection.

Chimney stacks	
Repair category	-
Notes	Not applicable.

Roofing including roof space	
Repair category	1
Notes	The roof coverings appear to be in reasonable order allowing for age and normal weathering. Some recent repair/maintenance works have been carried out. The manufacturers of modern roof tiles expect that a roof tile will normally last for approximately 50 years. This should be taken into consideration having regard to the age of this property.

Rainwater fittings	
Repair category	1
Notes	No obvious significant defects were was noted to the rainwater goods.
	Some recent repair/maintenance works have been carried out.
	It was not raining at the time of the inspection and it is therefore not possible to confirm that all joints are completely water tight.

Main walls	
Repair category	1
Notes	No obvious significant defects were noted to the main walls allowing for normal weathering.

Windows, external doors and joinery	
Repair category	1
Notes	No obvious significant defects were noted to the windows, door or other external joinery fixtures.

External decorations	
Repair category	1
Notes	The external decorations are mostly in reasonable condition but are beginning to deteriorate in places.

Conservatories/porches	
Repair category	-
Notes	Not applicable.

Communal areas	
Repair category	-
Notes	Not applicable.

Garages and permanent outbuildings	
Repair category	-
Notes	Not applicable.

Outside areas and boundaries	
Repair category	1
Notes	No obvious significant defects were noted to the outside areas or boundaries.
	There are some mature trees in close proximity of the building. No evidence of damage was noted. Ongoing maintenance will be required.
	We are not aware of any incidences of flooding at this location.

Ceilings	
Repair category	1
Notes	No obvious significant defects were noted to the ceilings.

Internal walls	
Repair category	1
Notes	No obvious significant defects were noted to the internal walls.

Floors including sub-floors	
Repair category	1
Notes	No obvious significant defects were noted to the floors, within the limitations of the inspection.

Internal joinery and kitchen fittings	
Repair category	1
Notes	No obvious significant defects were noted to the internal joinery fixtures or kitchen fittings.

Chimney breasts and fireplaces	
Repair category	-
Notes	Not applicable.

Internal decorations	
Repair category	1
Notes	No obvious significant defects were noted to the internal decorations. Some older forms of Artex have been known to contain asbestos fibres. Even so, a finish of this type is not normally considered a health hazard as any asbestos fibres would be encapsulated by the material however, appropriate cautions should be taken if removal is planned.

Cellars	
Repair category	-
Notes	Not applicable.

Repair category	1
Notes	No obvious significant defects were noted, however, only the most recently constructed or re- wired properties have installations which fully comply with current regulations. It is good practice to have electrical systems fully tested upon a change in ownership, where upgrading may be identified by the contractor.

Gas	
Repair category	1
Notes	It is recommended good practice that all gas installations should be checked periodically. This should be regarded as a routine safety and maintenance check.

<b>F</b> Water, plumbing and bathroom fittings	
Repair category 1	
Notes	No obvious significant defects were noted to the accessible plumbing fixtures or sanitary fittings.
	There is some wear to the tile grouting and seal around the shower. Any leakage around defective seals/grout will put concealed areas at risk of defects.

Heating and hot water	
Repair category	1
Notes	The system was not running at the time of inspection but appeared serviceable. It is recommended good practice that gas boilers are serviced on an annual basis by an appropriately qualified person. The boiler's service history should be checked by referring to the service records. If there is no record of a recent service, the boiler should be checked by an appropriately qualified person.

Drainage	
Repair category	1
Notes	No obvious significant defects were noted to the drainage system, within the limitations of the inspection.

Set out below is a summary of the condition of the property which is provided for reference only. You should refer to the previous comments for detailed information.

Structural movement	1
Dampness, rot and infestation	1
Chimney stacks	-
Roofing including roof space	1
Rainwater fittings	1
Main walls	1
Windows, external doors and joinery	1
External decorations	1
Conservatories/porches	-
Communal areas	-
Garages and permanent outbuildings	-
Outside areas and boundaries	1
Ceilings	1
Internal walls	1
Floors including sub-floors	1
Internal joinery and kitchen fittings	1
Chimney breasts and fireplaces	-
Internal decorations	1
Cellars	-
Electricity	1
Gas	1
Water, plumbing and bathroom fittings	1
Heating and hot water	1
Drainage	1

#### **Category 3**

Urgent repairs or replacement are needed now. Failure to deal with them may cause problems to other parts of the property or cause a safety hazard. Estimates for repairs or replacement are needed now.

#### Category 2

Repairs or replacement requiring future attention, but estimates are still advised.

#### Category 1

No immediate action or repair is needed.

#### Remember

The cost of repairs may influence the amount someone is prepared to pay for the property. We recommend that relevant estimates and reports are obtained in your own name.

#### Warning

If left unattended, even for a relatively short period, Category 2 repairs can rapidly develop into more serious Category 3 repairs. The existence of Category 2 or Category 3 repairs may have an adverse effect on marketability, value and the sale price ultimately achieved for the property. This is particularly true during slow market conditions where the effect can be considerable.

#### 3. Accessibility information

#### Guidance notes on accessibility information

Three steps or fewer to a main entrance door of the property:

In flatted developments the 'main entrance' would be the flat's own entrance door, not the external door to the communal stair. The 'three steps or fewer' are counted from external ground level to the flat's entrance door. Where a lift is present, the count is based on the number of steps climbed when using the lift.

#### Unrestricted parking within 25 metres:

For this purpose, 'Unrestricted parking' includes parking available by means of a parking permit. Restricted parking includes parking that is subject to parking restrictions, as indicated by the presence of solid yellow, red or white lines at the edge of the road or by a parking control sign, parking meters or other coin-operated machines.

1. Which floor(s) is the living accommodation on?	First
2. Are there three steps or fewer to a main entrance door of the property?	Yes X No
3. Is there a lift to the main entrance door of the property?	Yes No X
4. Are all door openings greater than 750mm?	Yes No X
5. Is there a toilet on the same level as the living room and kitchen?	Yes X No
6. Is there a toilet on the same level as a bedroom?	Yes X No
7. Are all rooms on the same level with no internal steps or stairs?	Yes No X
8. Is there unrestricted parking within 25 metres of an entrance door to the building?	Yes X No

#### 4. Valuation and conveyancer issues

This section highlights information that should be checked with a solicitor or licensed conveyancer. It also gives an opinion of market value and an estimated reinstatement cost for insurance purposes.

#### Matters for a solicitor or licensed conveyancer

The tenure is understood to be outright ownership.

The legal adviser should check existence and details of acceptable management arrangements service charges and block insurance.

The legal advisers should check whether there are any proposed works that will incur significant charges.

In line with our normal practice, it is specifically assumed that the property and its value are unaffected by any matters which would or should be revealed to a competent Completing Solicitor by a local search and replies to the usual enquiries, or by any statutory notice and planning proposal.

#### Estimated reinstatement cost for insurance purposes

£155,000 (One hundred and fifty five thousand pounds sterling).

The rebuilding cost for insurance purposes is for the subject property only and is given solely as a guide, as it is assumed the building as a whole is insured under a single policy.

#### Valuation and market comments

In its present condition the opinion of valuation for the Outright Ownership interest with vacant possession on the 20th November 2023 is £75,000 (Seventy five thousand pounds sterling).

Signed	Security Print Code [516585 = 5777 ] Electronically signed
--------	---

Report author	Thomas O'Kane

Company name	Harvey Donaldson and Gibson

Address	Room E101, Floor E, Marathon House, Olympic Business Centre, Kilmarnock, Ayrshire, KA2 9BE

Date of report	22nd November 2023

### Mortgage Valuation Report



Property Address	
Address Seller's Name Date of Inspection	17 Welbeck Street, Kilmarnock, KA1 3JN Ms L Craig 20th November 2023
Property Details	
Property Type	House     Bungalow     Purpose built maisonette     Converted maisonette       X Purpose built flat     Converted flat     Tenement flat     Flat over non-residential use       Other (specify in General Remarks)
Property Style	Detached     Semi detached     Mid terrace     End terrace       Back to back     High rise block     X Low rise block     Other (specify in General Remarks)
Does the surveyor be e.g. local authority, m	lieve that the property was built for the public sector, Yes X No ilitary, police?
Flats/Maisonettes only	y Floor(s) on which located 1 No. of floors in block 2 Lift provided? Yes X No No. of units in block 6
Approximate Year of (	
Tenure	
X Absolute Ownership	Leasehold   Ground rent £   Unexpired years
Accommodation	
Number of Rooms	1     Living room(s)     2     Bedroom(s)     1     Kitchen(s)       1     Bathroom(s)     1     WC(s)     0     Other (Specify in General remarks)
	cluding garages and outbuildings) 54 m <sup>2</sup> (Internal) 62 m <sup>2</sup> (External) greater than 40%) X Yes No
Garage / Parking / G	Outbuildings
Single garage Available on site?	Double garage     Parking space     X No garage / garage space / parking space       Yes     No
Permanent outbuilding	gs:
None.	

# Mortgage Valuation Report

Construction							
Walls	X Brick	Stone	Concrete	Timber frame	Other	(specify in Gen	eral Remarks)
Roof	X Tile	Slate	Asphalt	Felt	Other	(specify in Gen	eral Remarks)
Special Risks							
Has the property s	suffered struct	ural moveme	nt?			Yes	X No
If Yes, is this rece	nt or progress	ive?				Yes	No
Is there evidence, immediate vicinity		ason to antici	pate subsidence	e, heave, landslip o	or flood in the	Yes	X No
If Yes to any of the	e above, provi	de details in	General Remark	KS.			
Service Connec	tion						
Based on visual in of the supply in Ge			es appear to be	non-mains, pleas	e comment or	n the type ar	nd location
Drainage	X Mains	Private	None	Water	X Mains	Private	None
Electricity	X Mains	Private	None	Gas	X Mains	Private	None
Central Heating	X Yes	Partial	None				
Brief description o	f Central Heat	ting:					
Full gas system.							
Site							
Apparent legal iss	ues to be veri	fied by the co	onveyancer. Plea	ase provide a brief	f description ir	n General Re	emarks.
Rights of way	Shared drive	es / access	Garage or other	amenities on separate	e site 🗌 Share	ed service conn	ections
III-defined boundari	ies	Agricult	ural land included w	ith property	Other	(specify in Ge	neral Remarks)
Location							
Residential suburb	Res	idential within to	wn / city X Mixe	ed residential / comme	rcial Mainl	y commercial	
Commuter village	Ren	note village	Isol	ated rural property	Other	(specify in Ge	neral Remarks)
Planning Issues	;						
Has the property b			/ altered?	Yes X No			
If Yes provide deta	ails in Genera	l Remarks.					
Roads							
X Made up road	Unmade road	d Partly	completed new road	l Pedestrian a	access only	Adopted	Unadopted

#### **General Remarks**

When inspected within the imposed by occupation, the general condition of the property appears consistent with its age and type of construction, and no obvious significant defects were noted, which would adversely affect the subjects as a mortgage security.

#### **Essential Repairs**

None.			
Estimated cost of essential repairs £	Retention recommended? Yes	XNo	Amount £

# Mortgage Valuation Report

#### **Comment on Mortgageability**

The property affords adequate security for loan purposes based on the valuation figure, subject to individu	al
lender's criteria.	

Valuations	
Market value in present condition	£ 75,000
Market value on completion of essential repairs	£
Insurance reinstatement value (to include the cost of total rebuilding, site clearance, professional fees, ancillary charges plus VAT)	£ 155,000
Is a reinspection necessary?	Yes X No
Buy To Let Cases	
What is the reasonable range of monthly rental income for the property assuming a letting on a 6 month Short Assured Tenancy basis?	£
Is the property in an area where there is a steady demand for rented accommodation of this type?	Yes No
Declaration	

Signed	Security Print Code [516585 = 5777 ] Electronically signed by:-
Surveyor's name	Thomas O'Kane
Professional qualifications	MRICS
Company name	Harvey Donaldson and Gibson
Address	Room E101, Floor E, Marathon House, Olympic Business Centre, Kilmarnock, Ayrshire, KA2 9BE
Telephone	01563 852477
Fax	0203 880 9199
Report date	22nd November 2023

### **Energy Performance Certificate (EPC)**

# Scotland

#### Dwellings

#### 17 WELBECK STREET, KILMARNOCK, KA1 3JN

Dwelling type:	Top-floor flat
Date of assessment:	20 November 2023
Date of certificate:	20 November 2023
Total floor area:	54 m²
Primary Energy Indicator:	185 kWh/m²/year

#### **Reference number:** Type of assessment: Approved Organisation: Main heating and fuel:


2804-1902-9209-9787-9204 RdSAP, existing dwelling Elmhurst Boiler and radiators, mains das

#### You can use this document to:


- Compare current ratings of properties to see which are more energy efficient and environmentally friendly
- Find out how to save energy and money and also reduce CO<sub>2</sub> emissions by improving your home

Estimated energy costs for your home for 3 years*	£3,036	See your recommendations
Over 3 years you could save*	£438	report for more information

\* based upon the cost of energy for heating, hot water, lighting and ventilation, calculated using standard assumptions



Very environmentally friendly - lower CO<sub>2</sub> emissions



#### Energy Efficiency Rating

This graph shows the current efficiency of your home, taking into account both energy efficiency and fuel costs. The higher this rating, the lower your fuel bills are likely to be.

Your current rating is **band C (75)**. The average rating for EPCs in Scotland is band D (61).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Environmental Impact (CO<sub>2</sub>) Rating

This graph shows the effect of your home on the environment in terms of carbon dioxide (CO<sub>2</sub>) emissions. The higher the rating, the less impact it has on the environment.

Your current rating is **band C (77)**. The average rating for EPCs in Scotland is band D (59).

The potential rating shows the effect of undertaking all of the improvement measures listed within your recommendations report.

#### Top actions you can take to save money and make your home more efficient

Recommended measures	Indicative cost	Typical savings over 3 years
1 Increase loft insulation to 270 mm	£100 - £350	£234.00
2 Low energy lighting	£45	£207.00

A full list of recommended improvement measures for your home, together with more information on potential cost and savings and advice to help you carry out improvements can be found in your recommendations report.

To find out more about the recommended measures and other actions you could take today to stop wasting energy and money, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282

THIS PAGE IS THE ENERGY PERFORMANCE **CERTIFICATE WHICH MUST BE AFFIXED TO THE DWELLING AND NOT BE REMOVED UNLESS IT IS REPLACED WITH AN UPDATED CERTIFICATE** 

#### 17 WELBECK STREET, KILMARNOCK, KA1 3JN 20 November 2023 RRN: 2804-1902-9209-9787-9204

#### Summary of the energy performance related features of this home

This table sets out the results of the survey which lists the current energy-related features of this home. Each element is assessed by the national calculation methodology; 1 star = very poor (least efficient), 2 stars = poor, 3 stars = average, 4 stars = good and 5 stars = very good (most efficient). The assessment does not take into consideration the condition of an element and how well it is working. 'Assumed' means that the insulation could not be inspected and an assumption has been made in the methodology, based on age and type of construction.

Element	Description	Energy Efficiency	Environmental
Walls	Cavity wall, as built, insulated (assumed)	<b>★★★</b> ☆	★★★★☆
Roof	Pitched, 100 mm loft insulation	★★★☆☆	★★★☆☆
Floor	(another dwelling below)	—	_
Windows	Fully double glazed	★★★☆	★★★★☆
Main heating	Boiler and radiators, mains gas	★★★★☆	★★★★☆
Main heating controls	Programmer, room thermostat and TRVs	★★★☆	★★★★☆
Secondary heating	None	—	_
Hot water	From main system	<b>★★★</b> ☆	★★★★☆
Lighting	Low energy lighting in 18% of fixed outlets	★★☆☆☆	★★☆☆☆

#### The energy efficiency rating of your home

Your Energy Efficiency Rating is calculated using the standard UK methodology, RdSAP. This calculates energy used for heating, hot water, lighting and ventilation and then applies fuel costs to that energy use to give an overall rating for your home. The rating is given on a scale of 1 to 100. Other than the cost of fuel for electrical appliances and for cooking, a building with a rating of 100 would cost almost nothing to run.

As we all use our homes in different ways, the energy rating is calculated using standard occupancy assumptions which may be different from the way you use it. The rating also uses national weather information to allow comparison between buildings in different parts of Scotland. However, to make information more relevant to your home, local weather data is used to calculate your energy use, CO<sub>2</sub> emissions, running costs and the savings possible from making improvements.

#### The impact of your home on the environment

One of the biggest contributors to global warming is carbon dioxide. The energy we use for heating, lighting and power in our homes produces over a quarter of the UK's carbon dioxide emissions. Different fuels produce different amounts of carbon dioxide for every kilowatt hour (kWh) of energy used. The Environmental Impact Rating of your home is calculated by applying these 'carbon factors' for the fuels you use to your overall energy use.

The calculated emissions for your home are 32 kg  $CO_2/m^2/yr$ .

The average Scottish household produces about 6 tonnes of carbon dioxide every year. Based on this assessment, heating and lighting this home currently produces approximately 1.8 tonnes of carbon dioxide every year. Adopting recommendations in this report can reduce emissions and protect the environment. If you were to install all of these recommendations this could reduce emissions by 0.3 tonnes per year. You could reduce emissions even more by switching to renewable energy sources.

#### 17 WELBECK STREET, KILMARNOCK, KA1 3JN 20 November 2023 RRN: 2804-1902-9209-9787-9204

#### Estimated energy costs for this home

Estimated energy costs for this nome				
	Current energy costs	Potential energy costs	Potential future savings	
Heating	£1,866 over 3 years	£1,668 over 3 years		
Hot water	£633 over 3 years	£636 over 3 years	You could	
Lighting	£537 over 3 years	£294 over 3 years	save £438	
Тс	otals £3,036	£2,598	over 3 years	

These figures show how much the average household would spend in this property for heating, lighting and hot water. This excludes energy use for running appliances such as TVs, computers and cookers, and the benefits of any electricity generated by this home (for example, from photovoltaic panels). The potential savings in energy costs show the effect of undertaking all of the recommended measures listed below.

#### **Recommendations for improvement**

The measures below will improve the energy and environmental performance of this dwelling. The performance ratings after improvements listed below are cumulative; that is, they assume the improvements have been installed in the order that they appear in the table. Further information about the recommended measures and other simple actions to take today to save money is available from the Home Energy Scotland hotline which can be contacted on 0808 808 2282. Before carrying out work, make sure that the appropriate permissions are obtained, where necessary. This may include permission from a landlord (if you are a tenant) or the need to get a Building Warrant for certain types of work.

	Indiantivo anot	Typical saving	Rating after improvement		
Recommended measures	Indicative cost per year		Energy	Environment	
1 Increase loft insulation to 270 mm	£100 - £350	£78	C 76	C 79	
2 Low energy lighting for all fixed outlets	£45	£69	C 78	C 80	

#### Choosing the right improvement package

For free and impartial advice on choosing suitable measures for your property, contact the Home Energy Scotland hotline on 0808 808 2282 or go to www.greenerscotland.org.



#### About the recommended measures to improve your home's performance rating

This section offers additional information and advice on the recommended improvement measures for your home

#### 1 Loft insulation

Loft insulation laid in the loft space or between roof rafters to a depth of at least 270 mm will significantly reduce heat loss through the roof; this will improve levels of comfort, reduce energy use and lower fuel bills. Insulation should not be placed below any cold water storage tank, any such tank should also be insulated on its sides and top, and there should be boarding on battens over the insulation to provide safe access between the loft hatch and the cold water tank. The insulation can be installed by professional contractors but also by a capable DIY enthusiast. Loose granules may be used instead of insulation quilt; this form of loft insulation can be blown into place and can be useful where access is difficult. The loft space must have adequate ventilation to prevent dampness; seek advice about this if unsure. Further information about loft insulation and details of local contractors can be obtained from the National Insulation Association (www.nationalinsulationassociation.org.uk).

#### 2 Low energy lighting

Replacement of traditional light bulbs with energy saving bulbs will reduce lighting costs over the lifetime of the bulb, and they last many times longer than ordinary light bulbs. Low energy lamps and fittings are now commonplace and readily available. Information on energy efficiency lighting can be found from a wide range of organisations, including the Energy Saving Trust (http://www.energysavingtrust.org.uk/home-energy-efficiency/lighting).

#### Low and zero carbon energy sources

Low and zero carbon (LZC) energy sources are sources of energy that release either very little or no carbon dioxide into the atmosphere when they are used. Installing these sources may help reduce energy bills as well as cutting carbon.

LZC energy sources present: There are none provided for this home

#### Your home's heat demand

In this section, you can see how much energy you might need to heat your home and provide hot water. These are estimates showing how an average household uses energy. These estimates may not reflect your actual energy use, which could be higher or lower. You might spend more money on heating and hot water if your house is less energy efficient. The table below shows the potential benefit of having your loft and walls insulated. Visit https://energysavingtrust.org.uk/energy-at-home for more information.

Heat demand	Existing dwelling	Impact of loft insulation	Impact of cavity wall insulation	Impact of solid wall insulation
Space heating (kWh per year)	4,051	(692)	N/A	N/A
Water heating (kWh per year)	1,765			

#### 17 WELBECK STREET, KILMARNOCK, KA1 3JN 20 November 2023 RRN: 2804-1902-9209-9787-9204

#### About this document

This Recommendations Report and the accompanying Energy Performance Certificate are valid for a maximum of ten years. These documents cease to be valid where superseded by a more recent assessment of the same building carried out by a member of an Approved Organisation.

The Energy Performance Certificate and this Recommendations Report for this building were produced following an energy assessment undertaken by an assessor accredited by Elmhurst (www.elmhurstenergy.co.uk), an Approved Organisation Appointed by Scottish Ministers. The certificate has been produced under the Energy Performance of Buildings (Scotland) Regulations 2008 from data lodged to the Scottish EPC register. You can verify the validity of this document by visiting www.scottishepcregister.org.uk and entering the report reference number (RRN) printed at the top of this page.

Assessor's name:	Mr. Thomas O'Kane
Assessor membership number:	EES/016098
Company name/trading name:	Harvey Donaldson & Gibson Chartered Surveyors
Address:	Room E101 Marathon House Olympic Business Centre
	Kilmarnock
	KA2 9BE
Phone number:	01563852477
Email address:	frances.wilson@hdg.co.uk
Related party disclosure:	No related party

If you have any concerns regarding the content of this report or the service provided by your assessor you should in the first instance raise these matters with your assessor and with the Approved Organisation to which they belong. All Approved Organisations are required to publish their complaints and disciplinary procedures and details can be found online at the web address given above.

#### Use of this energy performance information

Once lodged by your EPC assessor, this Energy Performance Certificate and Recommendations Report are available to view online at www.scottishepcregister.org.uk, with the facility to search for any single record by entering the property address. This gives everyone access to any current, valid EPC except where a property has a Green Deal Plan, in which case the report reference number (RRN) must first be provided. The energy performance data in these documents, together with other building information gathered during the assessment is held on the Scottish EPC Register and is available to authorised recipients, including organisations delivering energy efficiency and carbon reduction initiatives on behalf of the Scottish and UK governments. A range of data from all assessments undertaken in Scotland is also published periodically by the Scottish Government. Further information on these matters and on Energy Performance Certificates in general, can be found at www.gov.scot/epc.

#### 17 WELBECK STREET, KILMARNOCK, KA1 3JN 20 November 2023 RRN: 2804-1902-9209-9787-9204

#### Advice and support to improve this property

There is support available, which could help you carry out some of the improvements recommended for this property on page 3 and stop wasting energy and money. For more information, visit greenerscotland.org or contact Home Energy Scotland on 0808 808 2282.

Home Energy Scotland's independent and expert advisors can offer free and impartial advice on all aspects of energy efficiency, renewable energy and more.





.,	1	-	
	ſ		9
		- 💉	

Property Address	17 welbeck street, Kilmarnock, Ka13jn
Vendor(s)	Miss Laura Craig
Completion Date of Property Questionnaire	
System Ref:	QV287882





#### Note for sellers

- Please complete this form carefully. It is important that your answers are correct.
- The information in your answers will help ensure that the sale of your house goes smoothly. Please answer each question with as much detailed information as you can.
- If anything changes after you fill in this questionnaire but before the date of entry for the sale of your house, tell your solicitor or estate agent immediately.

#### Information to be given to prospective buyer(s)

1.	Length of ownership					
	How long have you owned the property? 3years					
2.	Council Tax					
	Which Council Tax band is your property in?					
	A 🕺 B 🧭 C 😣 D 😣 E 😣 F 😣 G 😣 H 😣					
3.	Parking					
	What are the arrangements for parking at your property? Please tick all that apply?					
	Garage 😣 Allocated parking space 😣 Driveway 😣					
	Shared parking 🧭 On street 😣 Resident permit 😣					
	Metered parking 😣 Other (please specify):					
4.	Conservation area					
	Is your property in a designated Conservation Area (that is an area of special architectural or historical interest, the character or appearance of which it is desirable to preserve or enhance)?					
	Don't know 😵					
5.	Listed buildings					
	Is your property a Listed Building, or contained within one (that is a building recognised and approved as being of special architectural or historical interest)?					
	No 📀					
6.	Alterations/additions/extensions					
a.	During your time in the property, have you carried out any structural alterations, additions or extensions (for example, provision of an extra bath/shower room, toilet, or bedroom)?					
	No 📀					
(i)	If you have answered yes, please describe below the changes which you have made:					
(ii)	Did you obtain planning permission, building warrant, completion certificate and other Yes Source onsents for this work?					
(iv)	If you have answered yes, the relevant documents will be needed by the purchaser and you should give them to your solicitor as soon as possible for checking. If you do not have the documents yourself, please note below who has these documents and your solicitor or estate agent will arrange to obtain them:					



6.	Alterations/additions/extensions			
	Have you had replacement windows, doors, patio doors or double glazing installed in your	Yes 📎		
b.	property? If you have answered yes, please answer the three questions below	No 😣		
	Were the replacements the same shape and type as the ones you	Yes 🔗		
(i)	replaced?	No 🐼		
	Did the work involve any changes to the window or door openings?	Yes 🔇		
(ii)		No 🐼		
	Please describe the changes made to the windows doors, or patio doors (with approximate date	•		
	completed): Changed to new pvc windows from wooden ones fitted 2021/2022			
(iii)	<b>New front composite door fitted 2022</b> Please give any guarantees which you received for this work to your solicitor or estate agent			
(,	riease give any guarantees which you received for this work to your solicitor or estate agent			
7.	Central heating			
	Is there a central heating system in your property?	Yes 📎		
a.	(Note: a partial central heating system is one which does not heat all the main	No 😣		
a.	rooms of the property — the main living room, the bedroom(s), the hall and the bathroom).	Partial 🚫		
	If you have answered yes or partial – what kind of central heating is there?	Failiai 🐼		
	(Examples: gas-fired, solid fuel, electric storage heating, gas warm air) Gas			
	I <u>f you have answered yes</u> , please answer the three questions below			
(i)	When was your central heating system or partial central heating installed?	New boiler 5years		
(i)	When was your central nearing system of partial central nearing installed :	old		
	Do you have a maintenance contract for the central heating system?	Yes 😣		
(ii)		No 🥑		
	If you answered yes please give details of the company with whom you have a maintenance co	ntract		
(111)	When was your maintenance contract last renewed? (Please provide the month and year)			
(iii)				
8.	Energy Performance Certificate			
	Does your property have an Energy Performance Certificate which is less than 10 years old?	Yes 😣		
	than To years old?	No 🥑		
9.	Issues that may have affected your property			
2	Has there been any storm, flood, fire, or other structural damage to your	Yes 😣		
a.	property while you have owned it?	No 🧭		
	If you have answered yes is the damage the subject of any outstanding	Yes 😣		
	insurance claim?	No 😣		
	Are you aware of the existence of asbestos in your property?	Yes 😣		
b.		No 🧭		
	If you have answered yes please give details:			



10.	Services			
	Please tick which services are connected	ed to your property	and give details of	the supplier
	Service	Connected	Suppli	er
	Gas or liquid petroleum gas		Octopu	s
	Water mains or private water supply		Scottish v	vater
a.	Electricity		Octopu	s
	Mains drainage		Scottish v	vater
	Telephone	$\otimes$		
	Cable TV or satellite	$\otimes$		
	Broadband		Plusne	et
b.	Is there a septic tank at your property?			Yes 😵
D.	If you have answered yes please answ	wer the questions b	elow	No 🧭
	Do you have appropriate consents for the	ne discharge of you	Ir septic tank?	Yes 😣
(i)				No 😣
				Don't know 😵
	Do you have a maintenance contract fo	r your septic tank?		Yes 😵
(::)				No 😵
(ii)	If you answered yes please give details of the co	mpany with whom you l	have a maintenance cor	ntract
11.	Responsibilities for shared or comm	on areas		
	Are you aware of any responsibility to c			Yes 😣
	used jointly, such as repair of a shared drive, private road, boundary, or garden area?			No 🥑
а.				Don't know 😣
	If you answered yes please give details			
			,	
	Are you aware of any responsibility to c maintenance of the roof, common stairv	ontribute to the cos	t of repair and	Yes 🧭
			on aleas :	No 😣
b.				Don't know 🚫
	If you answered yes please give details			
	Yes		,	
C.	Has there been any major repair or repl during the time you have owned the bui		rt of the roof	Yes 😣
	, , , , , , , , , , , , , , , , , , ,	J		No 🥑
	Do you have the right to walk over any example to put out your bins, or to main			Yes 😣
d.		an you boundant		No ⊘
	If you answered yes please give details			



### **PROPERTY QUESTIONNAIRE**

11.	Responsibilities for shared or common areas	
	As far as you are aware, do any of your neighbours have the right to walk over your property, for example to put out their rubbish bin, or to maintain their boundaries?	Yes 😣 No 🔗
e.	I <mark>f you answered yes</mark> please give details	
	As far as you are aware, is there a public right of way across any part of your property? (public right of way is a way over which the public has a right to pass, whether or not the land is privately owned.)	Yes No 🐼
f.	<u>If you answered yes</u> please give details	
12.	Charges associated with your property	
	Is there a factor or property manager for your property?	Yes 😣
		No 🧭
a.	I <u>f you answered yes</u> please provide name and address and give details relating to deposits held	and charges
	Is there a common buildings insurance policy?	Yes 😣
		No 🥑
b.		Don't know 🚫
	If you answered yes is the cost of insurance included in your monthly/annual factor's charges?	Yes
		No
c.	Please give details of any other charges you have to pay on a regular basis for the up areas or repair works, for example to a residents' association, or maintenance or stair <b>None</b>	
13.	Specialist works	
	As far as you are aware, has treatment of dry rot, wet rot, damp or any	Yes 😣
	other specialist work ever been carried out to your property?	No ⊘
	If you answered yes please give further details	
a.		
	Do you have any guarantees for this work?	Yes 😣
		No 😣
	Guarantees are held by :	
	As far as you are aware, has any preventative work for dry rot, wet rot, or damp ever been carried out to your property?	Yes 😣
		No 📀
_	<u>If you answered yes</u> please give further details	
b.		
	Do you have any guarantees for this work?	Yes 😣
	Guarantoos are hold by :	No 🚫
	Guarantees are held by :	



14.	Guarantees					
	Are there any warranties or guarantees for any of the following					
a.		No	Yes	Don't know	With title deeds	Lost
(i) b.	Electrical work	0	8	8	8	8
(ii) b.	Roofing	8	8		8	⊗
(iii) b.	Central heating	<b>Ø</b>	8	⊗	8	⊗
(iv) b.	National House Building Council (NHBC)	<b>Ø</b>	8	$\otimes$	8	$\otimes$
(v) b.	Damp course	<b>Ø</b>	8	8	8	8
(vi)	Any other work or installation? (for example cavity wall insulation, underpinning, indemnity policy)		$\bigotimes$	$\bigotimes$	$\bigotimes$	$\bigotimes$
b.						
	Are there any outstanding claims under any of the guarantees listed at	oove?		Yes No 😣		
C.	If you answered yes please give details					
15.	Boundaries					
	Are you aware has any boundary of your property been moved ten years?	in the la	ast			es No ⊘
a.				Do	on't kno	
	<u>If you answered yes</u> please give details					



16.	Notices that affect your property	
	In the past three years have you ever receievd a notice :	
a.	Advising that the owner of a neighbouring property has made a planning application?	Yes No 🥑
b.	that affects your property in some other way?	Yes No 🥑
C.	that requires you to perform any maintenance, repairs, or improvements to the property?	Yes No 🥑
	If you answered yes to any of a-c above please give the notices to your so agent, including any notices which arrive at any time before the date of entry of your property	

Declaration by the seller(s) or other authorised body or person(s)

I/We confirm that the information on this form is true and correct to the best of my/our knowledge and belief.

Signatures:

L Craig

Date:





Room E101, Floor E, Marathon House, Olympic Business Centre, Kilmarnock KA2 9BE 01563 852477 kilmarnock.residential@hdg.co.uk